

# Distribution Report

## Monthly Report

January 2022

Distribution activities:

- Replaced water pump in skid steer and cleaned fuel tank out.

Water leaks repaired:

- 343 Marion Blvd
- 3030 16<sup>th</sup> Ave
- 18<sup>th</sup> St and 11<sup>th</sup> Ave

Hydrant maintenance: 1

Service taps: 5

Boxes measured: 5