

# Distribution Report

## Monthly Report

July 2022

Distribution activities:

Replaced piping under floor at site #5 well house

Start phase two of 8<sup>th</sup> St main project that has roughly 800' of 6" pipe

- Leak holes repaired: 2
- Repaired valve boxes: 2
- Hydrant maintenance: 1
- Hydrants turned: 20
- Service taps: 48
- Measure curb boxes: 48
- Hydrants loaded out: 2